


AKL-PT2 Test Procedure

Background information


1. Record probe serial number, date, time, temperature, and relative humidity

DC Resistance

1. Equipment needed:
 - 5 ¼ digit multimeter (example: Rohde & Schwarz HMC8012)
2. Set multimeter to resistance mode.
3. Touch tips of probes together and press “NULL” button to remove lead resistance.
4. Place one probe on tip-side ground contact and the other on the top flat of the SMA as shown. Wait for meter reading to stabilize and record R_gnd value.



5. Place one probe on tip-side signal contact and one on SMA center pin as shown. Wait for meter reading to stabilize and record R_sig value.




Connector Gaging


1. Equipment needed:
 - SMA gage set (ex: Mini-Circuits ACUDIAL-SMA)
2. Zero female pin gage against the gage master.
3. Measure female pin position and record FP value to nearest .0005" (12.7 μ m).
4. Repeat for female dielectric.

Open Circuit Return Loss / Impedance

1. Equipment needed:
 - Soldering gear
 - Test fixture
 - 2-port 6 GHz VNA (ex: PicoVNA 106) and SOLT standard set
 - Precision SMA male terminator (ex: Rosenberger 32S15R-1.0E3)
 - 5 lbf-in (0.565 Nm) torque wrench
2. Perform single port SOLT calibration on VNA port 1 per manufacturer procedure.
3. Apply 23.992 mm reference plane extension to VNA port 1 to shift reference plane to tip of probe.
4. Secure bottom side of probe to Stickvise with double-sided tape and solder tip of probe to 6mm open on fixture as shown.



5. Connect terminator to SMA on probe and VNA port 1 to SMA on fixture. Torque both connections to 5 lbf-in (0.565 Nm).



6. Record 1-port S-parameters as {probe serial}-zin.s1p.